

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 34-5CX (C34NW) Pad

Location #: 335095



Photo # 5354 From entrance to location



Photo # 5355 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC GMR 34-5CX (C34NW) Pad
Location #: 335095



Photo # 5356 Location



Photo # 5357 Wellhead sign laying on ground

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 34-5CX (C34NW) Pad

Location #: 335095



Photo # 5358 Wellhead sign laying on ground



Photo # 5359 Unmarked/improperly marked deadman

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 34-5CX (C34NW) Pad

Location #: 335095



Photo # 5360 Unmarked/improperly marked deadman



Photo # 5361 Unmarked deadman