

Inspection Photos
Location Name: J Brophy 25-27
API Number: 125-07494



1. Well sign on separator shed door.



2. View of wellhead.

Inspection Photos
Location Name: J Brophy 25-27
API Number: 125-07494



3. Shared gas meter shed.



4. Digital gas meter. Calibration log needs to be replaced.

Inspection Photos
Location Name: J Brophy 25-27
API Number: 125-07494



5. Produced water tank with faded label.



6. Produced water tank broken hatch cover.

Inspection Photos
Location Name: J Brophy 25-27
API Number: 125-07494



7. Location overview.



8. Location overview.