

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWSE

Location ID: 334870

Date: 11/2/2023



Location Entrance – Photo #07335



Wellheads – Photo #07336

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWSE

Location ID: 334870

Date: 11/2/2023



Nov 2, 2023 at 12:27:48
3555 CR-215
Parachute CO 81635
United States

Separators – Photo #07339



Nov 2, 2023 at 12:28:06
3555 CR-215
Parachute CO 81635
United States

Tank Battery – Photo #07340

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWSE

Location ID: 334870

Date: 11/2/2023



Insufficient Erosion Controls on Access Road – Photo #07334