

Interim & Stormwater Inspection

September 20, 2023

Operator: Renegade Oil & Gas # 74165

Location ID: 320644

Inspection Document # 709400571

Arapahoe County, CO

SWNE, 25 5S 65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
**Location Name: Lowry State 13-25 Well &
Tank Battery**
Location ID: 320644



Photo 1. Photo of location sign on site.



Photo 2. Photo of Tank battery. Photo taken facing east.

Inspection Photos
Location Name: Lowry State 13-25 Well &
Tank Battery
Location ID: 320644



Photo 3. Photo of erosion from stormwater along tank battery south side. Photo taken facing west.



Photo 4. Photo of check dam filled with sediment from stormwater erosion along tank battery south side. Photo taken facing west.

Inspection Photos

Location Name: Lowry State 13-25 Well &
Tank Battery
Location ID: 320644

Sep 20, 2023 at 1:57:03 PM
Aurora CO 80016
United States



Photo 5. Photo of erosion from stormwater along tank battery south side, and weeds (kochia & russian thistle) . Photo taken facing west.

Sep 20, 2023 at 1:57:36 PM
Aurora CO 80016
United States



Photo 6. Photo of check dam filled with sediment from stormwater erosion along tank battery south side. Sediment observed leaving location. Photo taken facing east.

Inspection Photos
Location Name: Lowry State 13-25 Well &
Tank Battery
Location ID: 320644



Photo 7. Photo of erosion from stormwater tank battery location onto adjacent lands. Photo taken facing east.



Photo 8. Photo of weeds (kochia & russian thistle) along edge of working pad and into interim reclaimed area. Photo taken facing northwest.

Inspection Photos
Location Name: Lowry State 13-25 Well &
Tank Battery
Location ID: 320644

Sep 20, 2023 at 1:58:07 PM
Aurora CO 80016
United States



Photo 9. Photo of weeds (kochia & russian thistle) along the north side of pad in interim reclaimed area. Photo taken facing southeast.

Sep 20, 2023 at 2:01:18 PM
Aurora CO 80016
United States



Photo 10. Photo of State 35-13 wellhead and weeds (kochia & russian thistle) in interim reclaimed area. Photo taken facing northeast.

Inspection Photos
Location Name: Lowry State 13-25 Well &
Tank Battery
Location ID: 320644



Photo 11. Photo taken of weeds (kochia & russian thistle) in interim reclaimed area from previous photo. Photo taken facing northeast.



Photo 12. Photo of erosion from stormwater leaving well pad onto adjacent lands. Photo taken facing west.

Inspection Photos
Location Name: Lowry State 13-25 Well &
Tank Battery
Location ID: 320644



Photo 13. Photo taken of weeds (cocklebur, kochia & russian thistle) in interim reclaimed area near wellhead working pad. Photo taken facing southeast.



Photo 14. Photo taken of undisturbed area for reference and vegetation comparison. Photo taken facing northeast.