

Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Location Name: SPRAGUE MULTI WELL PAD - NENE 6-0-9
Loc ID: 336136
Inspection: 702402465




Exhibit A

CA: Undesirable vegetation growing around the WH and fencing. Comply with Rule 606.

CA Resolution: Operator has addressed and appropriately cleared the identified weeds around WH and fencing comply with Rule 606.