

Inspection Photos
Location Name: Hewitt 22-3 D
Location ID: 321380



Photo 1 well head and equipment



Photo 2 well head and equipment

Inspection Photos
Location Name: Hewitt 22-3 D
Location ID: 321380



Photo 3 separator stack



Photo 4 separator stack

Inspection Photos
Location Name: Hewitt 22-3 D
Location ID: 321380




Photo 5 production equipment



Photo 6 tank battery

Inspection Photos

Location Name: Hewitt 22-3 D
Location ID: 321380



Station #	Ad	Gr	Station Name	Sec	TwnShip	Range
10166A			Hewitt MD 22-3A	22	15	69.5
Radio #	Producer Name		Meter Tube Size	County	State	
	8 North		3.070	Boilder	Colo	
Transmitter / Module #	Federal #	State #				
Static/ Span	Up/Down	Diff/ Span	Temp/ Span	Absolute	API #	
D-500	UP	D-250	D-150	13.3		
Test Date	OP Size	Beta	Sample Date	H2S	OP Inspection	New Plate
6/15/17	1.250	.407	6/15/17	N/A	YES	YES 1.250
11/10/17	1.250	.407	11/30/17			1275.332
5/14/18	1.250	.407			5/14/18	NO
			11-28-18 MSA			1275.21
						180.69

Nov 6, 2023 11:42:10 AM
+39.9506N -105.1066W
161° S
Broomfield County
Energy & Carbon Management Commission

Photo 7 meter calibration card

