

Operator: EXTRACTION OIL & GAS
Location Name: HEWIT-61S69W 22NWSW
Loc ID: 321380
Inspection: 713300267



Exhibit A

CA: Mechanical issues, stack for heater in need of repair. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

CA Resolution: The fire stack for heater has been removed to comply with Rule 608.e.