

**Operator: 8 NORTH LLC**

**Location Name: DF RANCH1161-9-24 TANK**

**Loc ID: 431338**

**Inspection: 696300570**

Inspection Photos  
Location Name: DF Ranch 9-24 Tank  
Location ID: 431338



Photo 3 – Tank Capacity has Faded.



Photo 4 – Tank

Exhibit A

**CA:** All 4 Tank and Water Vault Capacity Labels have faded no longer visibly, see photo 2, 3 & 4.

**CA Resolution:** New Inspections and follow-up have been completed regarding this location; however, it was noted during a review that there was an open Inspection from 2019 involving a missing capacity label on an identified tank. It was recently requested that the Operator review the location and identified tank to ensure that this signage was installed. Operation was able to confirm and provide photo evidence that this appropriate signage on the identified tank had been installed to display the capacity.