

Inspection Photos

Location Name: CAERUS PICEANCE LLC, TATE FEDERAL-66S99W/30NENE

Location ID: 322480

Date: 11/8/2023



Location Entrance – Photo #07391




Wellhead – Photo #07394

Inspection Photos

Location Name: CAERUS PICEANCE LLC, TATE FEDERAL-66S99W/30NENE

Location ID: 322480

Date: 11/8/2023



Separator – Photo #07398



Tank Battery – Photo #07392

Inspection Photos

Location Name: CAERUS PICEANCE LLC, TATE FEDERAL-66S99W/30NENE

Location ID: 322480

Date: 11/8/2023



Debris – Photo #07393



Unprotected Soil Stockpile – Photo #07395

Inspection Photos

Location Name: CAERUS PICEANCE LLC, TATE FEDERAL-66S99W/30NENE

Location ID: 322480

Date: 11/8/2023



Unprotected Soil Stockpile – Photo #07396