

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-67S96W/7NWNE

Location ID: 334577

Date: 11/9/2023



Location Entrance – Photo #07460



Wellhead – Photo #07463

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-67S96W/7NWN

Location ID: 334577

Date: 11/9/2023



Separator – Photo #07462



Tank Battery – Photo #07461