

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403590484

Date Received:

11/10/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 5 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10810

Name of Operator: MESSER LLC

Address: 200 SOMERSET CORP BLVD #7000

City: BRIDGEWATER State: NJ Zip: 08807

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>DeMarco, Jaime</u>		<u>jdemarco@blm.gov</u>
<u>Engineering, General</u>		<u>dnr_ecmc_engineering@state.co.us</u>
<u>Pienta, Brad</u>	<u>(908) 952-4528</u>	<u>Brad.pienta@messer-us.com</u>
<u>Hom, Brian</u>	<u>(908) 771-1625</u>	<u>Brian.hom@messer-us.com</u>
<u>Twitty, Melita</u>	<u>(908) 771-1894</u>	<u>Melita.twitty@messer-us.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Hartman, Laura</u>		<u>lhartman@blm.gov</u>

OGCC INSPECTION SUMMARY:

FIR Document Number: 712700785

Inspection Date: 10/25/2023

FIR Submit Date: 10/26/2023

FIR Status: _____

Inspected Operator Information:

Company Name: MESSER LLC

Company Number: 10810

Address: 200 SOMERSET CORP BLVD #7000

City: BRIDGEWATER State: NJ Zip: 08807

LOCATION - Location ID: 313551

Location Name: AIRCO DUDLEY-N36N18W Number: 13NWSW County: MONTEZUMA

Qtrqr: NWS Sec: 13 Twp: 36N Range: 18W Meridian: N
W

Latitude: 37.373650 Longitude: -108.788083

FACILITY - API Number: 05-083- -00 Facility ID: 224457

Facility Name: AIRCO DUDLEY Number: 5

Qtrqr: NWS Sec: 13 Twp: 36N Range: 18W Meridian: N
W

Latitude: 37.373650 Longitude: -108.788083

CORRECTIVE ACTIONS:

1 ☒ CA# 187066

Corrective Action: Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).

Date: 11/10/2023

Response: CA COMPLETED

Date of Completion: 11/10/2023

Operator Comment: Meter calibration record now displayed. Photo attached as 'Dudley meter calibration'.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 187067

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).

Date: 11/10/2023

Response: CA COMPLETED

Date of Completion: 11/10/2023

Operator Comment: Valve was buried in dirt. Dirt has now been removed to expose valve. Valve in need of maintenance for operation--team working towards correction. Will advise once valve is operational. Photo attached of exposed valve as 'Dudley Bradenhead Valve'.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Submitted CA's 187066 & 187067. CA 187068 was submitted on 11/9/23 and approved on 11/10/23.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brian Hom

Signed:

Title: CO2 Product Manager

Date: 11/10/2023 4:44:56 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403590484	FIR RESOLUTION SUBMITTED
403592452	Dudley Meter Calibration
403592474	Dudley Bradenhead Valve

Total Attach: 3 Files