

Inspection Photos
Location Name: Cook 37C-3HZ
Location ID: 429708



Energy & Carbon Management Commission
40.14754, -104.64932, 1460.3m, 62°
Nov 13, 2023 10:33:13

Photo 1: Pumpjack sign




Energy & Carbon Management Commission
40.14756, -104.64937, 1462.1m, 108°
Nov 13, 2023 10:33:30

Photo 2: Pumpjack



Inspection Photos
Location Name: Cook 37C-3HZ
Location ID: 429708



Energy & Carbon Management Commission
40.14754, -104.64933, 1459.1m, 68°
Nov 13, 2023 10:33:19

Photo 3: Stained soil



Energy & Carbon Management Commission
40.14747, -104.64928, 1462.6m, 44°
Nov 13, 2023 10:33:50

Photo 4: Wellhead

Inspection Photos
Location Name: Cook 37C-3HZ
Location ID: 429708



Photo 5: Wellhead



Photo 6: Wellhead



Inspection Photos
Location Name: Cook 37C-3HZ
Location ID: 429708



Photo 7: Location



Photo 8: Tank Battery

Inspection Photos
Location Name: Cook 37C-3HZ
Location ID: 429708



Photo 9: Debris



Photo 10: Debris

Inspection Photos
Location Name: Cook 37C-3HZ
Location ID: 429708



Photo 11: Debris



Photo 12: Debris

Inspection Photos
Location Name: Cook 37C-3HZ
Location ID: 429708



Photo 13: Debris



Photo 14: Debris

Inspection Photos
Location Name: Cook 37C-3HZ
Location ID: 429708



Photo 15: Debris



Photo 16: Debris