

## Inspection Photos

Location Name: Bockius 15-8, 8, Pfannebecker C14-32, C15-22 Tank Battery

Facility ID: 447609



**Tank Battery**



**Production Equipment**





## Inspection Photos

Location Name: Bockius 15-8, 8, Pfannebecker C14-32, C15-22 Tank Battery

Facility ID: 447609



**Unmarked risers in multiple spots need to be marked by identifying what they are and tagged with OOSLAT**



**Unused Equipment**



## Inspection Photos

Location Name: Bockius 15-8, 8, Pfannebecker C14-32, C15-22 Tank Battery

Facility ID: 447609



**Unused Equipment**



**Unused Equipment**

## Inspection Photos

Location Name: Bockius 15-8, 8, Pfannebecker C14-32, C15-22 Tank Battery

Facility ID: 447609



**Unused Equipment**



**Unused Equipment**



## Inspection Photos

Location Name: Bockius 15-8, 8, Pfannebecker C14-32, C15-22 Tank Battery

Facility ID: 447609



November 13, 2023 at 8:14 AM

+40.3128, -104.5276

38° NE

Weld County

Energy & Carbon Management Commission

**Unused Equipment**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources