

Inspection Photos
Location Name: Stonehocker 23-7
Location ID: 333088



Photo 1 P&A well head and excavation



Photo 2 P&A well excavation

Inspection Photos
Location Name: Stonehocker 23-7
Location ID: 333088



Photo 3 excavation



Photo 4 excavation

Inspection Photos
Location Name: Stonehocker 23-7
Location ID: 333088



Photo 5 unused equipment



Photo 6 stock pile

Inspection Photos
Location Name: Stonehocker 23-7
Location ID: 333088



Photo 7 excavation with storm water

Photo 8 excavation with storm water