

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FORSTER W-46-11 Pad

Location ID: 323781



Photo # 6440 From entrance to location




Photo # 6441 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FORSTER W-46-11 Pad

Location ID: 323781



Photo # 6442 Location



Photo # 6443 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FORSTER W-46-11 Pad

Location ID: 323781



**Photo # 4059 From inspection 708902036 conducted on 10/24/2023 Unmarked deadman**

**Photo # 6444 Unmarked deadman**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FORSTER W-46-11 Pad

Location ID: 323781



Photo # 4060 From inspection 708902036 conducted on 10/24/2023 Same unmarked deadman from a different angle



Photo # 6445 Same unmarked deadman from a different angle

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FORSTER W-46-11 Pad

Location ID: 323781



Photo # 6446 Debris