

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: VICKLUND G-61N69W 2SWNE

Loc ID: 321459

Inspection: 713300279



Exhibit E

CA: Dead overgrown vegetation, Comply with Rule 606

CA Resolution: Operator has addressed the identified dead, ungrown vegetation and weed debris to comply with Rule 606.