


Caerus Piceance LLC
Piceance Creek Unit T21X-19G
Location ID: 316261



Entrance sign



Debris

Caerus Piceance LLC
Piceance Creek Unit T21X-19G
Location ID: 316261



Dry hole plate



Debris

**Caerus Piceance LLC
Piceance Creek Unit T21X-19G
Location ID: 316261**



Location from Northeast corner



Location from Southeast corner

**Caerus Piceance LLC
Piceance Creek Unit T21X-19G
Location ID: 316261**



Location from Southwest corner



Location from Northwest corner