

## **Storm Water Management and Erosion control**

**Location Name: MUSTANG RESOURCES LLC CLOUGH FEDERAL 14-24A-6S-94W**

**Location ID: 311543**



**Location Overview: Location is within High Priority/Density  
Habitat areas & in close proximity to Bald Eagle Roost Site.**

**Section/Township/Range: 14 6S94W**



## Storm water Management and Erosion control

**Location Name: MUSTANG RESOURCES LLC CLOUGH FEDERAL 14-24A-6S-94W**

**Location ID: 311543**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Storm water Management and Erosion control**  
**Location Name: MUSTANG RESOURCES LLC CLOUGH FEDERAL 14-24A-6S-94W**  
**Location ID: 311543**



**Photo # 6490 Erosion & transport of sediment**



**Photo # 6491 Erosion & transport of sediment**



## Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC CLOUGH FEDERAL 14-24A-6S-94W

Location ID: 311543



Photo # 6492 Erosion & transport of sediment



Photo # 6493 Erosion & transport of sediment