

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT RMV 16-35 Pad

Location ID: 323890



Photo # 6648 From entrance to location



Photo # 6649 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT RMV 16-35 Pad

Location ID: 323890



Photo # 6650 Location



Photo # 6651 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT RMV 16-35 Pad

Location ID: 323890



Photo # 6652 Location



Photo # 6653 Debris