

Work Completion Report

Contractor: Peerless

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
LORENZ FEDERAL #1		Armando Munoz	10/26/2023

Work Summary	Reclamation Type	Land Use
We address and repaired erosion on northern and central portions of the tank battery	Stormwater	Pasture

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Stormwater Repairs	High	Yes	Location(s): LORENZ FEDERAL 1 Notes: Address and repair erosion on norther and central portions of the tank battery.

COMPLETION DETAILS

Total Area Affected: **0.22 acres**
Seed Mix: **None used**
Crop Type:
Soil Type: **Clay Loam**
Stabilization Date: **10/26/2023**
Seeding Date:
Mulch: **None**
Straw Bales: **NA**
Soil Amendment Type: **None**
Soil Amendment Rate: **NA**
Imported Top Soil: **NA**
Top Soil Source: **NA**
General Notes:

LOCATION INFO

Location(s) – Name: LORENZ FEDERAL 1

COGCC ID: **318057**
Well APIs at Location: **12308306**
Land Rep: **David Bell**
Land Owner: **Magness**
Rec Contractor PO(s): **M&E - TBD**
Vendor PO(s):
Billing Notes: **DJ-L0882**
Legal Address: **(WELD) SWSW 30 3N66W**
Topsoil Source:
Variance Notes:
Private Utility Notes:
Wildlife Restrictions: **None**
General Notes:
COGCC Doc #'s:
Initial Reclaim Complete Date:
Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Site Map

Description:



Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:



Photo Name: Lorenzo2

Description:



Photo Name: Lorenzo3

Description:



Photo Name: Lorenzo4

Description:



Photo Name: Lorenzo5

Description:

