



01092988

WELL SITE INSPECTION FORM

WELL NAME Coltharp API NUMBER 05 - 103 -
OPERATOR Auroquest PERMIT NUMBER 89
LOCATION NENW 1/4, IN, 10242 COUNTY Rio Blanco
FIELD Rangel - Marcos INSPECTOR KTB

AL/PA/DA INSPECTION RESULTS:

WELL STATUS:

PASS(Y) _____ FAIL(N) _____ DATE _____ FN _____ FD ☒ WO _____

=====

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____

CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____

RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION 5/17/90

PIPE SET? yes COMPLETION RIG/ACTIVITY None

DRILLING PITS: CLOSED _____ OPEN ☒ ^{lined} WELLHEAD SYSTEM INSTALLED No

TANK ID: YES _____ NO _____ NA ☒ WELL SIGN: YES _____ NO ☒

SKIM PIT: _____ gal TANKS: () _____ bbls

EQUIPMENT None

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____

METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA ☒ SI _____ WELL CAT 3- D

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____

HOLE PLUGGED: YES _____ NO _____ PITS BACKFILLED: YES _____ NO _____

MATERIAL BURIED: YES _____ NO _____ NA _____ SITE CLEAN: YES _____ NO _____

BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO _____

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS 7" capped casing at surface. 80' from road to west, 180' to road on south side. In town limits. Not fenced. St cutting mounds & pieces of 7" casing next to hole.

✓