

Inspection Photos
Location Name: Craig #3
Location ID: 329626



Photo 1 – Pumping Unit



Photo 2 – Well Sign

Inspection Photos
Location Name: Craig #3
Location ID: 329626



Photo 3 – Pumping Unit – Weeds



Photo 4 – Weeds at Wellhead

Inspection Photos
Location Name: Craig #3
Location ID: 329626



Photo 5 – Wellhead – Weeds