

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 1 – Pumping Unit

Photo 2 – Well Sign

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Energy and Carbon Management Commission
40.71856, -103.66265, 4437.4ft
11/21/2023 11:37:58



Energy and Carbon Management Commission
40.71863, -103.66275, 4452.6ft
11/21/2023 11:36:49

Photo 3 – Wellhead – Stained Soil

Photo 4 – Heater Treater

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 5 – Skim Tank



Photos 6 – Pits