

Inspection Photos
Location Name: Northrup 1-14-OWP
Location ID: 327106



Photo 1 – Location Overview – All Production Equipment has been removed



Photo 2 – Location Overview – All Production Equipment has been removed

Inspection Photos
Location Name: Northrup 1-14-OWP
Location ID: 327106



Photo 3 – Gas Line



Photo 4 – Wellhead

Inspection Photos
Location Name: Northrup 1-14-OWP
Location ID: 327106



Photo 5 – Wellhead Sign

