

Work Completion Report

Contractor: Jamm Power Services

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
KELLY 1A (2023 Seasonal)	Spring	Jamm Power	6/26/2023

Work Summary	Reclamation Type	Land Use
Mowed	Final Maint	Pasture

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Spring Mowing	Normal	No	Location(s): KELLY 1A Notes: May include innerseeding, mowing, spraying, debris clean-up. If locates and red zone are required, please notify Oxy to modify job assignment and schedule on-site meeting. If the location does not need work completed, please complete a work completion report. If location is ready for Form 4, please complete inspection and add Form 4 work task

COMPLETION DETAILS

Total Area Affected: **43,560 sq ft**
Seed Mix: **None used**
Crop Type:
Soil Type: **Clay Loam**
Stabilization Date:
Seeding Date:
Mulch: **None**
Straw Bales: **NA**
Soil Amendment Type: **None**
Soil Amendment Rate: **NA**
Imported Top Soil: **NA**
Top Soil Source: **NA**
General Notes:

LOCATION INFO

Location(s) – Name: KELLY 1A

COGCC ID: **318739**
Well APIs at Location: **12309848**
Land Rep: **None established**
Land Owner:
Rec Contractor PO(s): **Jamm Power PO:4501167939**
Vendor PO(s): **Buffalo Brand Seed PO:4501173751**
Billing Notes: **O22-00638.01.10**
Legal Address: **(WELD) NESW 7 2N66W**
Topsoil Source:
Variance Notes:
Private Utility Notes:
Wildlife Restrictions:
General Notes:
COGCC Doc #'s:
Initial Reclaim Complete Date:
Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Site Map

Description:



Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:

