

Inspection Photos
Location Name: Henderson #2
Location ID: 405711



Photo 1 – Pumping Unit



Photo 2 – Well Sign

Inspection Photos
Location Name: Henderson #2
Location ID: 405711



Photo 3 – Wellhead



Photo 4 – Chemical Tank – Label has faded no longer visible