

Inspection Photos
Location Name: Rasmussen 1
Location ID: 333138



Photo 1 Location.

Photo 2 WH sign.

Inspection Photos
Location Name: Rasmussen 1
Location ID: 333138



Photo 3 WH.



Photo 4 unused pump jack stacked by the well.

Inspection Photos
Location Name: Rasmussen 1
Location ID: 333138



Photo 5 unused pump jack stacked by the well.