


Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29SWNE

Location ID: 335298

Date: 11/27/2023



Nov 27, 2023 at 10:22:38
8311 CR-215
Parachute CO 81650
United States



Nov 27, 2023 at 10:23:01
8311 CR-215
Parachute CO 81650
United States

Location Entrance – Photo #07667

Wellheads – Photo #07668

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29SWNE

Location ID: 335298

Date: 11/27/2023



Separators – Photo #07669



Tank Battery – Photo #07670

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29SWNE

Location ID: 335298

Date: 11/27/2023



Insufficient Cut Slope Erosion Controls – Photo #07671