

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324123

Date: 11/27/2023



Nov 27, 2023 at 10:28:50  
3555 CR-215  
Parachute CO 81635  
United States

Location Entrance – Photo #07673



Nov 27, 2023 at 10:29:11  
3555 CR-215  
Parachute CO 81635  
United States

Wellhead – Photo #07674



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324123

Date: 11/27/2023



Separator – Photo #07678




Tank Battery – Photo #07676

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324123

Date: 11/27/2023



Wellhead Sign Missing API Number – Photo #07675