

Final Reclamation Inspection

November 10th, 2023

Operator: BP America Production Company -
10000

Location ID: 325407

Inspection Document #: 714000130

La Plata County, CO

Township: NWNE 8 32N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WIRT D 1E
Location ID: 325407



Photo 1. View of the project area taken from the entrance facing center.

Inspection Photos
Location Name: WIRT D 1E
Location ID: 325407




Photo 2. Cardinal photos taken from the middle of the project area.
Left photo facing north, right photo facing east.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06326

Inspection Photos
Location Name: WIRT D 1E
Location ID: 325407



Photo 3. Cardinal photos taken from the middle of the project area.
left photo facing south, right photo facing west.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06326

Inspection Photos
Location Name: WIRT D 1E
Location ID: 325407



Photo 4. View of bare ground lacking vegetation in the southern portion of the project area that needs additional reclamation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06326

Inspection Photos
Location Name: WIRT D 1E
Location ID: 325407



Photo 5. Reference area comprised of sagebrush, rabbit brush and squirrel tail.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06326