

Final Reclamation and Stormwater Inspection

Date: 11/17/23

Operator: Noble Energy Inc. - 100322

Location ID: 329529

Inspection Document #: 713900102

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Duncan D #11-14
Location ID: 329529



Photo 1. The photo was taken at the access road entrance facing Southwest. The photo illustrates the access road is dominated by russian thistle and cheatgrass.

Photo 2. The photo was taken at the well location facing North. The photo illustrates the location is dominated by russian thistle and cheatgrass with bunches of wheatgrass.

Inspection Photos
Location Name: Duncan D #11-14
Location ID: 329529



Photo 3. The photo was taken at the well location facing East.
Refer to the comments on photo 2.

Photo 4. The photo was taken at the well location facing East.
Refer to the comments on photo 2.

Inspection Photos
Location Name: Duncan D #11-14
Location ID: 329529



Photo 5. The photo was taken at the well location facing East. Refer to the comments on photo 2.



Photo 6. The photo was taken North of the well location facing South.

Inspection Photos
Location Name: Duncan D #11-14
Location ID: 329529



Photo 7. The photo was taken at the tank battery entrance facing South. The photo illustrates the area is dominated by russian thistle and kochia.



Photo 8. The photo was taken on the tank battery location facing East. The photo illustrates the location is dominated by bare soil, kochia and russian thistle.