

Inspection Photos

Location Name: TREBOR B-65N64W/11NESW

Location ID: 310599



Photo #1

Trebor B 11-25 (123-26657) Wellsite

Temporarily Abandoned | TA

CA: Overgrown Vegetation



Photo #2

Trebor B 11-25 Battery site

Inactive | Shut-down

Formerly served:

Trebor B11-13, B11-14 ;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 310599



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources