

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA/14-6 Pad

Location ID: 335035

Date: 11/30/2023



West End of Location – Photo #07761



East End of Location – Photo #07753

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA/14-6 Pad

Location ID: 335035

Date: 11/30/2023



Wellheads – Photo #07757



Separators – Photo #07756

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA/14-6 Pad

Location ID: 335035

Date: 11/30/2023



Tank Battery – Photo #07754



Stained Soil – Photo #07758

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA/14-6 Pad

Location ID: 335035

Date: 11/30/2023



Stained Soil – Photo #07759



Stained Soil – Photo #07760