

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/36SWSE

Location ID: 335010

Date: 11/28/2023



Wellheads – Photo #07768



Separators – Photo #07771



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/36SWSE

Location ID: 335010

Date: 11/28/2023



**Tank Battery – Photo #07772**



**Lack of Stabilization – Photo #07770**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/36SWSE

Location ID: 335010

Date: 11/28/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit**  
– Photo #07773