

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 11/30/2023



Location Entrance – Photo #07775



Wellheads – Photo #07776

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 11/30/2023



Separators – Photo #07779



Tank Battery – Photo #07777

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 11/30/2023



Lack of Stabilization – Photo #07778



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #07780