

Final Reclamation Inspection

November 30th, 2023

Operator: Simcoe LLC - 10749

Location ID: 326640

Inspection Document #: 714000173

La Plata County, CO

Township: SESE 20 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Arthur B Maason 2
Location ID: 326640




Photo 1. View of the project area taken from the entrance facing center.

Inspection Photos
Location Name :Arthur B Maason 2
Location ID: 326640



Photo 2. Pile of soil observed in the northern portion of the disturbance. This is considered debris and needs to be removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515



Photo 3. Pile of wood debris observed on the western edge of the disturbance.



Inspection Photos
Location Name : Arthur B Maason 2
Location ID: 326640



Photo 4. View of impacted soils observed on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name : Arthur B Maoson 2
Location ID: 326640



Photo 5. Interim vegetation was not fully assessed due to snowy conditions.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515