

**Inspection Photos**  
**Location Name: Pronghorn B-24 PAD**  
**Location ID: 437037**



**Photo 1 – Signs at Entrance**



**Photo 2 – Gas Lift Injection Meter House**



**Inspection Photos**  
**Location Name: Pronghorn B-24 PAD**  
**Location ID: 437037**



**Photo 3 – Separators**



**Photo 4 – Tumbleweed Debris at Pipe Rack**



**Inspection Photos**  
**Location Name: Pronghorn B-24 PAD**  
**Location ID: 437037**



**Photo 5 – Tank Battery**



**Photo 6 – Tank Battery Signs**



**Inspection Photos**  
**Location Name: Pronghorn B-24 PAD**  
**Location ID: 437037**



**Photo 7 – Tank Battery**



**Photo 8 – ECDs**



**Inspection Photos**  
**Location Name: Pronghorn B-24 PAD**  
**Location ID: 437037**




**Photo 9 – Back Side of South Tanks**



**Photo 10 – Water Tank NFPA and Capacity Labels**

**Inspection Photos**  
**Location Name: Pronghorn B-24 PAD**  
**Location ID: 437037**



**Photo 11 – Wellheads**



**Photo 12 – C-W-24HNB – Risers not OOSLAT**



**Inspection Photos**  
**Location Name: Pronghorn B-24 PAD**  
**Location ID: 437037**



**Photo 13 – 11-41-24HNC Wellhead**

