

# Interim Reclamation and Stormwater Inspection

Date: 11/29/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 319123

Inspection Document #: 708200721

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Gold 1  
Location ID: 319123



**Photo 1.** Trash and debris observed at the start of the access road.



Inspection Photos  
Location Name: Gold 1  
Location ID: 319123



**Photo 2.** Taken south of the tank battery. Photo illustrates the presence of Colorado List B Noxious weed (canada thistle) observed on location.



Inspection Photos  
Location Name: Gold 1  
Location ID: 319123



**Photo 3.** Taken south of the tank battery. Photo illustrates the presence of Colorado List B Noxious weed (common teasel) observed on location.





**Photo 4.** Emergency contact label is beginning to peel/crack/fade and is illegible; replacement required.





**Photo 5.** Debris and trash observed on the east side of the location. Also pictured, Colorado List B Noxious weed (russian olive) observed to be growing throughout the location.



Inspection Photos  
Location Name: Gold 1  
Location ID: 319123



**Photo 6.** Trash and debris observed south of the tank battery.





**Photo 7.** Taken south of the location. Photo illustrates Colorado List B Noxious weed (russian olive) growing throughout the location.