

Interim Reclamation and Stormwater Inspection

Date: 11/27/2023

Operator: Phoenix Resources LLC - 10691

Location ID: 420020

Inspection Document #: 713900131

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Cass Farms #11-25H
Location ID: 420020



Photo 1. The photo taken from the entrance of the location illustrating the Operator signage.



Photo 2. The photo was taken from the well location facing North. The photo illustrates weeds on the location have still been mostly unmanaged from the previous corrective action.

Inspection Photos
Location Name: Cass Farms #11-25H
Location ID: 420020



Photo 3. The photo was taken from the well location facing North. Refer to the comment for photo 2.



Photo 4. The photo was taken from the well location facing Northwest. The photo illustrates some weeds have been mowed.

Inspection Photos
Location Name: Cass Farms #11-25H
Location ID: 420020



Photo 5. The photo was taken from the West side of the well location facing North. Refer to the comment for photo 2.



Photo 6. The photo was taken from the East side of the well location facing Northwest. Refer to the comment for photo 2.

Inspection Photos
Location Name: Cass Farms #11-25H
Location ID: 420020



Photo 7. The photo was taken from the well location facing North. The photo illustrates stained soil from a previous corrective action that have not been corrected.



Photo 8. The photo was taken from the well location facing Southeast. The photo illustrates some of the trash that has not been picked up from a previous corrective action.