

Inspection Photos

Location Name: CAERUS PICEANCE LLC, NPR/H15-596

Location ID: 425805

Date: 12/4/2023



Location Entrance – Photo #07860



Wellheads – Photo #07853

Inspection Photos

Location Name: CAERUS PICEANCE LLC, NPR/H15-596

Location ID: 425805

Date: 12/4/2023



Wellheads – Photo #07857



Gas Meters – Photo #07851



Inspection Photos

Location Name: CAERUS PICEANCE LLC, NPR/H15-596

Location ID: 425805

Date: 12/4/2023



Gas Meters – Photo #07858



Tank Battery/No Battery Sign – Photo #07855

Inspection Photos

Location Name: CAERUS PICEANCE LLC, NPR/H15-596

Location ID: 425805

Date: 12/4/2023



Chemical Tanks – Photo #07850



Chemical Tanks – Photo #07859