

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/22NWSE

Location ID: 335794

Date: 12/4/2023



Location Entrance – Photo #07888



Wellheads – Photo #07893



Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/22NWSE

Location ID: 335794

Date: 12/4/2023



Gas Meters – Photo #07892



Gas Meters – Photo #07889

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/22NWSE

Location ID: 335794

Date: 12/4/2023



Tank Battery/No Battery Sign Posted – Photo #07890

