

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. Parachute/WF K22 596

Location ID: 335648

Date: 12/4/2023



Location Entrance – Photo #07896



Wellheads – Photo #07898

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. Parachute/WF K22 596

Location ID: 335648

Date: 12/4/2023



Mobile Separator Units – Photo #07897



Gas Meters – Photo #07899

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. Parachute/WF K22 596

Location ID: 335648

Date: 12/4/2023



Gas Meters/Tank Battery – Photo #07900



Tank Battery/No Battery Sign Posted – Photo #07901

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. Parachute/WF K22 596

Location ID: 335648

Date: 12/4/2023



Chemical Tanks – Photo #07902



Pig Station – Photo #07903