

# Inspection Photos

Loc: 309389

Operator: OGRIS OPERATING LLC

Inspection Date: 12/5/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the wellsite.



## Inspection Photos



**Photo 2.** There is stained soil shown at red arrow that needs to be cleaned up. It appears fluids were released at this area.



## Inspection Photos



**Photo 3.** Facing toward the production equipment. There is a panel laying on the ground and unused piping at red arrows..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:309389 | Date: 12/5/2023

## Inspection Photos



**Photo 4.** The engine skid is full of oil and has spilled onto the ground..

