

# Inspection Photos

Loc: 309138

Operator: OGRIS OPERATING LLC

Inspection Date: 12/5/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east toward the wellsite.




## Inspection Photos



**Photo 2.** Facing toward the production equipment.



## Inspection Photos



**Photo 3.** There is stained soil next to the engine skid.



## Inspection Photos



**Photo 4.** The fence around the lined pi is in disrepair.

