

Inspection Photos

12/05/2023

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335512

Inspection Doc: 696205440

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335512



Photo 1: Photos 1-2 taken from the east end of the WPS. Photos provide an overview of the Location from south, southwest, northwest to north.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335512



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335512



Photo 3: Tank battery facility. Signage per 605.e not posted.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources