

Inspection Photos
Location Name: State Pronghorn 34-12 PAD
Location ID: 431418



Photo 1 – Wellheads



Photo 2 – Wellheads

Inspection Photos
Location Name: State Pronghorn 34-12 PAD
Location ID: 431418



Photo 3 – Separators



Photo 4 – Second Separator from the East is open to Atmosphere

Inspection Photos
Location Name: State Pronghorn 34-12 PAD
Location ID: 431418



Photo 5 – Gas Lift Injection Meters and Line Heater

Photo 6 – Instrumental Air Unit

Inspection Photos
Location Name: State Pronghorn 34-12 PAD
Location ID: 431418



Photo 7 – Signs at Entrance