

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-15 Pad

Location ID: 335571



Photo # 8303 From entrance to location



Photo # 8304 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-15 Pad

Location ID: 335571



Dec 4, 2023 at 11:14:15 AM
CO

Photo # 8305 Location



Dec 4, 2023 at 11:14:34 AM
CO

Photo # 8306 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-15 Pad

Location ID: 335571



Photo # 8307 Location



Photo # 8308 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-15 Pad

Location ID: 335571



Photo # 8309 Stained soils & gravel



Photo # 8310 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-15 Pad

Location ID: 335571



Photo # 8311 Tank label weathered & illegible