

**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC CHRISTNER 8-6 (F8E) Pad**  
**Location ID: 324052**



**Location Overview: Location is within High  
Priority/Density/NSO/Black Bear Habitat areas. Location is  
approximately 125 yards from West Mamm Creek & 291 yards  
from Middle Mamm Creek.**

**Section/Township/Range: 8 7S92W**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC CHRISTNER 8-6 (F8E) Pad**  
**Location ID: 324052**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC CHRISTNER 8-6 (F8E) Pad**  
**Location ID: 324052**



**Photo # 8983 Tunnel erosion**



**Photo # 8984 Tunnel erosion**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC CHRISTNER 8-6 (F8E) Pad**  
**Location ID: 324052**



**Photo # 8985 Tunnel erosion**



**Photo # 8986 Rip Rap Run needs maintenance - stormwater is eroding & undercutting Rip Rap Run**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC CHRISTNER 8-6 (F8E) Pad**  
**Location ID: 324052**



**Photo # 8987 Erosion & transport of sediment off location**



**Photo # 8988 Erosion & transport of sediment off location**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC CHRISTNER 8-6 (F8E) Pad**  
**Location ID: 324052**



**Photo # 8989 Erosion & transport of sediment off location**