

Inspection Photos

Location Name: CAERUS PICEANCE LLC CHRISTNER 8-6 (F8E) Pad

Location ID: 324052



Photo # 8972 From entrance to location



Photo # 8973 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC CHRISTNER 8-6 (F8E) Pad

Location ID: 324052



Dec 7, 2023 at 3:27:53 PM
CO

Photo # 8974 Location



Dec 7, 2023 at 3:24:31 PM
CO

Photo # 8975 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC CHRISTNER 8-6 (F8E) Pad

Location ID: 324052



Photo # 8976 Location



Photo # 8977 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC CHRISTNER 8-6 (F8E) Pad

Location ID: 324052



Photo # 8978 Weeds/Undesirable plant species



Photo # 8979 Weeds/Undesirable plant species

Inspection Photos

Location Name: CAERUS PICEANCE LLC CHRISTNER 8-6 (F8E) Pad

Location ID: 324052



Photo # 8980 Weeds/Undesirable plant species



Photo # 8981 Unmarked deadman

Inspection Photos

Location Name: CAERUS PICEANCE LLC CHRISTNER 8-6 (F8E) Pad

Location ID: 324052



Photo # 8982 Same unmarked deadman from a different angle