

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36G-795 Pad

Location ID: 324300



Photo # 8736 From entrance to location



Photo # 8737 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36G-795 Pad

Location ID: 324300



Photo # 8738 Location



Photo # 8739 Location



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36G-795 Pad

Location ID: 324300



Photo # 8740 Location



Photo # 8741 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36G-795 Pad

Location ID: 324300



**Photo # 8742 Methanol tank label weathered & illegible /improperly labeled/lacks required information (tank near separator)**



**Photo # 8743 Methanol tank improperly labeled/lacks required information (tank near separator)**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36G-795 Pad

Location ID: 324300



**Photo # 8744 Methanol tank label weathered & illegible/improperly labeled/lacks required information (tank near separator)**



**Photo # 8745 Methanol tank improperly labeled/lacks required information (tank near wellhead)**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36G-795 Pad

Location ID: 324300



**Photo # 8746 Methanol tank improperly labeled/lacks required information (tank near wellhead)**



**Photo # 8747 Methanol tank improperly labeled/lacks required information (tank near wellhead)**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36G-795 Pad

Location ID: 324300



**Photo # 8748 Methanol tank lacks secondary containment  
(tank near separator)**

